F40 - FLUX CORE ARC WELDING (FCAW), E308LT, Section 12.19 Table 12.19-1 of AP-42 (1/95)

CALCULATION METHODS (for Trace Metals with listed AP-42 emission factors)

 $Ea = Ua \times EF (lbs/lb \text{ rod})$

 $Eh = Uh \times EF (lbs/lb rod)$

CALCULATION METHODS (for Trace Metals without listed AP-42 emission factors)

Ea = Ua x EF (Fume generation rate lbs fume/lb rod x NASSCO Fume Correction Factor) x Ci

Eh = Uh x EF (Fume generation rate lbs fume/lb rod x NASSCO Fume Correction Factor) x Ci

NOTES:

Default Electrode

- All emissions are assumed uncontrolled. Control efficiencies must be included in the release point information if applicable.
- Trace metals with specified emission factors listed by the EPA in AP-42 are quantified accordingly.
- Trace metals which are components of the welding rod but not identified by EPA will be quantified by the District's default procedures.
- Default fume generation rates (lbs fume/lb rod) are; 0.01 (GMAW, TIG, & MIG), 0.02 (SMAW & FCAW), and 0.05 (unspecified).
- Default Fume Correction Factors from NASSCO (Dr. Bell) are 0.5464 (GMAW, TIG, & MIG), 0.2865 (SMAW & FCAW), and 1.0 (unspecified).
- Default hexavalent chromium conversion rates from ARB analysis of AWS data are; 0.05 (GMAW, TIG, & MIG), 0.63 (SMAW & FCAW), and 0.10 (unspecified).
- Trace metal EPA emission factors for specific rods are from Tables 12.19-1 & 12.19-2 (1/95) of AP-42.

POLLUTANT	District Emission Factor	EPA REFERENCE	EPA	(UNITS)	COMMENTS
	(lbs/lb rod)	DOCUMENT	FACTOR		
NOX					
CO					
SOX					
TOG					
ROG					
TSP	9.10E-03				ASSUME PM10 = TSP
PM10	9.10E-03	Table 12.19-1 (1/95) AP-42	9.10	1b/1000 lbs rod	ASSUME PM10 EMISSION RATE = FUME GENERATION RATE (FGR)
Chromium, Nonhexavalent	= 9.65E-04 x Ci	District / ARB / NASSCO Procedure	ND	0.1 lb/1000 lbs rod	EMISSIONS = Ua x FGR x 0.2865 x Ci x (1 - 0.63)
Chromium, Hexavalent	= 1.64E-03 x Ci	District / ARB / NASSCO Procedure	ND		EMISSIONS = Ua x FGR x 0.2865 x Ci x 0.63
Cobalt	= 2.61E-03 x Ci	District / ARB / NASSCO Procedure	ND		EMISSIONS = Ua x FGR x 0.2865 x Ci
Manganese	= 2.61E-03 x Ci	District / ARB / NASSCO Procedure	ND		EMISSIONS = Ua x FGR x 0.2865 x Ci
Nickel	= 2.61E-03 x Ci	District / ARB / NASSCO Procedure	ND		EMISSIONS = Ua x FGR x 0.2865 x Ci
Lead	= 2.61E-03 x Ci	District / ARB / NASSCO Procedure	ND		EMISSIONS = Ua x FGR x 0.2865 x Ci
Metals w/o Emission Factors	= 2.61E-03 x Ci	District / ARB / NASSCO procedure	ND		EMISSIONS = Ua x FGR x 0.2865 x Ci

Composition	Weight %	Reference	
Aluminum			
Chromium, Total	21.00%	Based on MSDS 7922-H	
Cobalt			
Copper			
Lead			
Manganese	1.50%	Based on MSDS 7922-H	
Nickel	10.00%	Based on MSDS 7922-H	
Zinc			

Last Updated on 8/26/99 By D. Byrnes